DISCREPANCY REPORT

DISTRICT #	SERIAL # _ XVE-7625
CARRIER CO 716	· Andrews
DRIVER Sared Tia	PICK - UP DATE 9-4-15
Total Control of the	
P THE FOLLOWING ITEMS WERE NOTED WHE	N THE MACHINE WAS PICKED - UP FROM THE
T MISSING	
1 DAMAGE damaged finish	
Dent lateling	wast an am
Dent locking bracket for fix	righer
IMPROPERLY DESERVICED BY	DRIVER
	The same of the sa
OTHER	
OTHER	
The state of the s	
的现在分词,可是是"自然的"。	\$P\$\$P\$\$P\$· 195 \$1 · \$\$ \$1 · \$ \$1 · \$ \$1 · \$ \$1 · \$1 ·
	DATE
THE FOLLOWING ITEMS WERE NOTED WHEN THE	E MACHINE WAS BEING PREPARED FOR
METOHN TO XEHOX:	
PARTS, KITS REMOVED BY DISTRICT	
OTHER	